

Requisitos granulométricos del agregado grueso

Tamaño Nominal (mm.)	Porcentaje que pasa por los tamices normalizados												
	100 mm	90 mm	75 mm	63 mm	50 mm	37.5 mm	25 mm	19 mm	12.5 mm	9.5 mm	4.75 mm	2.36 mm	1.18 mm
90.0 a 37.5 (3 1/2" a 1 1/2")	100	90-100		25-60		0-15		0-5					
63.0 a 37.5 (2 1/2" a 1 1/2")			100	90-100	35-70	0-15		0-5					
50.0 a 25.0 (2" a 1")				100	90-100	35-70	0-15		0-5				
50.0 a 4.75 (2" a #4)				100	95-100		35-70		10-30		0-5		
37.5 a 19.0 (2 1/2" a 3/4")					100	90-100	20-55	0-15		0-5			
37.5 A 4.75 (1 1/2" a #4)					100	95-100		35-70		10-30	0-5		
25.0 a 12.5 (1" a 1 1/2")						100	90-100	20-55	0-10	0-5			
25.0 a 9.50 (1" a 3/8")						100	90-100	40-85	10-40	0-15	0-5		
25.0 a 4.75 (1" a #4)						100	95-100		25-60		0-10	0-5	
19.0 a 9.50 (3/4" a 3/8")							100	90-100	20-55	0-15	0-5		
19.0 a 4.75 (3/4" a #4)							100	90-100		20-55	0-10	0-5	
12.5 a 4.75 (1/2" a #4)								100	90-100	40-70	0-15	0-5	
9.50 a 2.36 (3/8" a #8)									100	85-100	10-30	0-10	0-5